
NOTICE TO MARINERS

No. H. 90/2019

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 2nd July 2019 shows the following: -

- 1) Depths of between 4.9 metres and 5.5 metres below Chart Datum have encroached up to 205 metres into the East side of the channel from 625 metres downstream of the No. 15A Light Buoy to 220 metres downstream of the No. 17 North Holme Light Float.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 5.4 metres and 5.5 metres below Chart Datum have encroached up to 20 metres into the West side of the channel from 170 metres downstream to 110 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 41/2019 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

3rd July 2019

LOCAL NOTICE TO MARINERS FOR 2014, 2015, 2017, 2018 & 2019 CURRENTLY IN FORCE:

H. 50/2014, H. 42/2015, H. 158/2017, H. 09/2018, H. 76/2018, H. 87/2018, H.194/2018, H. 02/2019, H. 07/2019, H. 11/2019, H. 18/2019, H. 21/2019, H. 23/2019, H. 25/2019, H. 27/2019, H. 35/2019, H. 37/2019, H. 44/2019, **H. 61/2019**, H. 69/2019, H. 70/2019, H. 73/2019, H. 75/2019, H. 78/2019, H. 79/2019, H. 81/2019, **H. 83/2019**, H. 84/2019, **H. 87/2019**, H. 88/2019, H. 89/2019, H.90/2019

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com