
NOTICE TO MARINERS

No. H. 92/2017

U P P E R H U M B E R

MOVES OF FLOATING MARKS AND SHOAL WATER

NOTICE IS HEREBY GIVEN that it is proposed on Thursday 13th July 2017 (or as soon after as circumstances permit) to move: -

- 1) The Middle Whitton Light Float to a position 087° T., 942 metres from the Whitton Ness Beacon.

Latitude 53° 42.880' N, Longitude 0° 35.786' W (WGS 84)

- 2) The No. 33A Light Float to a position 030° T., 1420 metres from the Whitton Ness Beacon.

Latitude 53° 43.520' N, Longitude 0° 35.996' W (WGS 84)

- 3) The No. 32C Light Buoy to a position 274° T., 2570 metres from the Whitton Ness Beacon.

Latitude 53° 42.952' N, Longitude 0° 38.974' W (WGS 84)

The Middle Whitton Light Float will then bear 319° T., 865 metres from the No. 33 Light Float.

The No. 33A Light Float will then bear 349° T., 1208 metres from the new position of the Middle Whitton Light Float and 092° T., 1076 metres from the No. 32B Light Float.

The No. 32C Light Buoy will then bear 034° T., 1022 metres from the No. 34 Light Buoy and 241°T., 1503 metres from the Upper Whitton Light Float.

MARINERS ARE WARNED that on completion of the above moves, the following shoal water will exist: -

- 1) A least depth of 0 metres at Chart Datum exists close North of the ships course 280 metres downstream of the Lower Whitton Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

- 2) A least depth of 0.2 metres **ABOVE** Chart Datum exists 90 metres North of the ships course 975 metres upstream of the Upper Whitton Light Float.

Deeper water exists on the ships course in this vicinity

- 3) A least depth of 0.4 metres **ABOVE** Chart Datum exists close South of the ships course 250 metres downstream of the No. 32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 91/2017 is hereby cancelled.

MARINERS ARE FURTHER ADVISED that on completion of the above moves 0.2 metres below Chart Datum should be used for passage planning and Notice to Mariners No. H. 89/2017 will be cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

12th July 2017

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com