

NOTICE TO MARINERS

No. H. 05/2022

R I V E R H U M B E R

FOUL HOLME CHANNEL FH2 BUOY – RETURNED TO STATION

MARINERS ARE ADVISED that the FH2 Buoy has been returned to station in its original charted position:

Latitude: 53° 38.520 ' N Longitude: 0° 09.928' W (WGS84)

Light Characteristics: Fl.R.2s

MARINERS ARE FURTHER ADVISED that Notice to Mariners No. H. 02/2022 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

6th January 2022

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.