

NOTICE TO MARINERS

No. H. 07/2025

RIVER HUMBER

MAJOR ALTERATION OF BULL CHANNEL – MOVE OF NO 5 GATE BUOY AND ALTERATION OF HAWKE ANCHORAGE


NOTICE IS HEREBY GIVEN that on Monday 13th January 2025, or as soon after as circumstances permit there will be a major alteration to the Bull Channel.

This will involve the move of the No. 5 Gate Buoy to a position approximately 430 metres North East of its original charted position to a new position as follows:

Latitude 53° 35.107' N Longitude 0° 3.943' E (WGS 84)

- Characteristics: FI.G.4s
- Green Conical mark

MARINERS ARE ADVISED that the following Hawke anchorage positions will be discontinued: Hotel (H), India (I), Juliet (J), Kilo (K), Lima (L), Mike (M)



H.07/2025 Page 1 of 2



MARINERS ARE REMINDED that strong tidal sets can be experienced in this area and advised to navigate with caution in this vicinity.

CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

10th January 2025

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com