
NOTICE TO MARINERS

No. H. 102/2024

RIVER HUMBER

HALTON MIDDLE - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 19th and 20th August 2024 show the following: -

- 1) Depths of between 5.3 metres and 5.5 metres below Chart Datum have encroached up to 75 metres into the Eastern edge of the channel from 380 metres downstream to 670 metres upstream of the No. 15A Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) Depths of between 5 metres and 5.5 metres below Chart Datum have encroached up to 65 metres into the Western edge of the channel from 720 metres downstream to 560 metres upstream of the No. 14 Skitter Haven Light Buoy.

Deeper water exists to the East in this vicinity.

- 3) Depths of between 5 metres and 5.5 metres below Chart Datum have encroached up to 10 metres into the Western edge of the channel from 670 metres to 930 metres upstream of the No. 16 Sand End Light Buoy.

Deeper water exists to the East in this vicinity.

MARINERS ARE ADVISED that 5.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 64/2024 is hereby cancelled.

CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER

22nd August 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com