
NOTICE TO MARINERS

No. H. 104/2023

H U M B E R A P P R O A C H E S

INNER TRAFFIC SEPARATION SCHEME (INBOUND LANE) - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 26th and 27th July 2022 and 10th June and 9th August 2023 show the following: -

- 1) Depths of between 7.2 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 160 metres into the Northern buoy-line of the Inward Traffic Separation Scheme (TSS) Lane, from 460 metres East-North-East of the No. 3 Chequer South Cardinal Buoy to 265 metres West-South-West of the Spurn Light Float.

Deeper water exists to the South in this vicinity.

- 2) Depths of between 6.6 metres below Chart Datum and 10.7 metres below Chart Datum have encroached up to 780 metres into the Southern buoy-line of the Inward Traffic Separation Scheme (TSS) Lane, from 2000 metres East-North-East of the Alpha Buoy to 1040 metres East of the Bravo Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED to navigate with caution in this area and Notice to Mariners No. H. 90/2023 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

14th August 2023