

NOTICE TO MARINERS

No. H. 113/2022

U P P E R H U M B E R

SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 3rd and 4th August 2022 show the following: -

- 1) A least depth of 2.2 metres **ABOVE** Chart Datum exists North of the ships course 220 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

- 2) A least depth of 0 metres at Chart Datum exists South of the ships course 75 metres downstream of the No. 33A Light Float.

Deeper water exists on the ships course in this vicinity.

MARINERS ARE ADVISED that 0.2 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 112/2022 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

4th August 2022

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com