

# **NOTICE TO MARINERS**

### No. H. 119/2023

## RIVER HUMBER

#### SUNK DREDGED CHANNEL – LEAST AVAILABLE DEPTH, SHOAL WATER AND RULING DEPTH

**MARINERS ARE WARNED** that surveys carried out on the 29<sup>th</sup> August, 6<sup>th</sup> September and 11<sup>th</sup> September 2023 indicate that a Least Available Depth (LAD) of 8.2 metres below Chart Datum exists in the Sunk Dredged Channel in the following area(s): -

Depths of less than 8.6 metres below Chart Datum have encroached up to 11.0 metres into the Southern edge of the channel from 530 metres to 660 metres upstream of the P7 Light Buoy.

MARINERS ARE ADVISED that 8.6 metres below Chart Datum is the Ruling Depth for the Sunk Dredged Channel and as such this figure should be used for passage planning purposes. In addition, Notice to Mariners No. H. 117/2023 is hereby cancelled.

#### CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

11<sup>th</sup> September 2023

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners. www.humber.com