

---

# **NOTICE TO MARINERS**

---

**No. H. 127/2022**

## **RIVER HUMBER**

### **SKITTER CHANNEL – SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 6<sup>th</sup> September 2022 show the following: -

A least depth of 0.5 metres **ABOVE** Chart Datum exists North of the ships course from 25 metres downstream to 250 metres upstream of the No. 20A Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 80/2022 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

7<sup>th</sup> September 2022

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)