
NOTICE TO MARINERS

No. H. 130/2022

RIVER HUMBER

HULL ROADS – EAST MIDDLE - SHOAL WATER

MARINERS ARE WARNED that a survey carried out on the 12th September 2022 shows the following: -

- 1) Depths of between 4.8 metres and 5.5 metres below Chart Datum have encroached up to 30 metres into the Northern edge of the channel from 115 metres downstream to 415 metres upstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of between 4.1 metres and 5.5 metres below Chart Datum have encroached up to 130 metres into the Southern edge of the channel from 45 metres downstream of the East Middle Light Buoy to the No. 24 Lower West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

MARINERS ARE ADVISED that Notice to Mariners No. H. 98/2022 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

12th September 2022

LOCAL NOTICE TO MARINERS FOR 2019, 2020, 2021 & 2022 CURRENTLY IN FORCE:

H. 27/2019, H. 43/2020, H. 67/2020, H. 68/2020, H. 160/2020, H. 02/2021, H. 07/2021, H. 24/2021, H. 43/2021, H. 64/2021, H. 92/2021, H. 109/2021, H. 178/2021, H. 179/2021, H. 08/2022, H. 12/2022, H. 19/2022, H. 22/2022, H. 27/2022, H. 28/2022, H. 37/2022, H. 50/2022, H. 54/2022, H. 67/2022, H. 68/2022, H. 75/2022, H. 82/2022, H. 89/2022, H. 90/2022, H. 95/2022, H. 99/2022, H. 103/2022, H. 104/2022, H. 108/2022, H. 109/2022, H. 110/2022, H. 111/2022, H. 115/2022, H. 118/2022, H. 120/2022, H. 121/2022, H. 125/2022, H. 126/2022, H. 127/2022, H. 128/2022, H. 129/2022, H. 130/2022.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com