

NOTICE TO MARINERS

No. H. 149/2023

RIVER HUMBER

**GRIMSBY MIDDLE DEPOSIT
SHOAL WATER**

MARINERS ARE WARNED that surveys carried out on the 6th to 14th November 2023 show the following: -

A shoal with a least depth of 1.1 metres below Chart Datum exists in the South-East corner of the Grimsby Middle deposit spoil ground, from 475 metres upstream of the P6 Light Buoy to 250 metres downstream of the P7 Light Buoy.

MARINERS ARE ADVISED that depths within spoil grounds are inevitably subject to change and should therefore proceed with caution in these areas. In addition, Notice to Mariners No. H. 73/2023 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

21st November 2023

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com