
NOTICE TO MARINERS

No. H. 178/2021

R I V E R H U M B E R

HUMBER LIGHT FLOAT REPLACEMENT

NOTICE IS HEREBY GIVEN that on Friday 17th December 2021, or as soon after as circumstances permit, the temporary Humber Light Float (see NTM No. H. 18/2019) will be replaced with a Green Conical Buoy. The buoy will be stationed in the same charted position and will exhibit the same light characteristics as before.

Position: Latitude: 53° 38.700' N Longitude: 0° 21.240' E (WGS 84)

Characteristics: LFl.G.10s
Green conical buoy

MARINERS ARE WARNED that the new buoy will **NOT** feature name boards, it will **NOT** broadcast its position via AIS and there will be **NO** Racon (T) fitted.

MARINERS ARE ADVISED that Notice to Mariners No. H. 18/2019 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

17th December 2021

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.
www.humber.com