

---

# **NOTICE TO MARINERS**

---

**No. H. 31/2024**

**RIVER HUMBER**

**GRIMSBY MIDDLE DEPOSIT  
SHOAL WATER**

**MARINERS ARE WARNED** that surveys carried out on the 8<sup>th</sup> & 14<sup>th</sup> November 2023 and 29<sup>th</sup> February 2024 show the following: -

A shoal with a least depth of 1.1 metres below Chart Datum exists in the South-East corner of the Grimsby Middle deposit spoil ground, from 475 metres upstream of the P6 Light Buoy to 250 metres downstream of the P7 Light Buoy.

**MARINERS ARE ADVISED** that depths within spoil grounds are inevitably subject to change and should therefore proceed with caution in these areas. In addition, Notice to Mariners No. H. 149/2023 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

29<sup>th</sup> February 2024

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)