

# **NOTICE TO MARINERS**

### No. H. 79/2024

## UPPER HUMBER

### SHOAL WATER

**MARINERS ARE WARNED** that surveys carried out on the 24<sup>th</sup> June 2024 show the following: -

1) A least depth of 2 metres <u>ABOVE</u> Chart Datum exists North of the ships course 460 metres downstream of the Lower Whitton Light Float.

Deeper water exists on the ships course in this vicinity.

2) Depths of between 0 metres at Chart Datum to 0.4 metres <u>ABOVE</u> Chart Datum exists North of the ships course in the vicinity of the No. 31 Light Float.

Deeper water exists on and to the South of the ships course in this vicinity.

 A least depth of 0.9 metres <u>ABOVE</u> Chart Datum exists North of the ships course 360 metres upstream of the No.33 Light Float.

Deeper water exists on the ships course in this vicinity.

4) A least depth of 0.2 metres <u>ABOVE</u> Chart Datum exists South of the ships course in the vicinity of the No.33A Light Float.

Deeper water exists on the ships course in this vicinity.

5) A least depth of 0.2 metres <u>ABOVE</u> Chart Datum exists North of the ships course 250 metres upstream of the No.32C Light Buoy.

Deeper water exists on the ships course in this vicinity.

**MARINERS ARE ADVISED** that 0.2 metres at Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 75/2024 is hereby cancelled.

#### CAPT. A. FIRMAN HARBOUR MASTER, HUMBER

24<sup>th</sup> June 2024