
NOTICE TO MARINERS

No. H. 80/2022

RIVER HUMBER

SKITTER CHANNEL – SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 19th, 20th and 25th May 2022 show the following: -

A least depth of 0.4 metres **ABOVE** Chart Datum exists North of the ships course from 345 metres to 475 metres upstream of the No. 20A Light Float.

Deeper water exists on the ships course in this vicinity.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

26th May 2022

LOCAL NOTICE TO MARINERS FOR 2019, 2020, 2021 & 2022 CURRENTLY IN FORCE:

H. 27/2019, H. 43/2020, H. 67/2020, H. 68/2020, H. 160/2020, H. 02/2021, H. 07/2021, H. 24/2021, H. 43/2021, H. 64/2021, H. 92/2021, H. 109/2021, H. 133/2021, H. 178/2021, H. 179/2021, H. 08/2022, H. 12/2022, H. 19/2022, H. 22/2022, H. 27/2022, H. 28/2022, H. 36/2022, H. 37/2022, H. 43/2022, H. 50/2022, H. 52/2022, H. 54/2022, H. 59/2022, H. 60/2022, H. 64/2022, H. 65/2022, H. 67/2022, H. 68/2022, H. 70/2022, H. 71/2022, H. 75/2022, H. 76/2022, H. 77/2022, H. 78/2022, H. 79/2022, H. 80/2022.

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com