

---

# **NOTICE TO MARINERS**

---

**No. H.82/2022**

## **RIVER HUMBER**

### **BULL CHANNEL - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 26<sup>th</sup> May 2022 shows the following:-

A shoal of between 2.4 metres and 5.5 metres below Chart Datum extends up to 915 metres into the channel from 930 metres downstream to 1650 metres upstream of the North Fort Cardinal Buoy.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 36/2022 is hereby cancelled.

**CAPT. A. FIRMAN.  
HARBOUR MASTER, HUMBER**

27<sup>th</sup> May 2022

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)