
NOTICE TO MARINERS

No. H. 94/2024

RIVER HUMBER

FOUL HOLME CHANNEL - SHOAL WATER

MARINERS ARE WARNED that surveys carried out on the 29th and 31st July 2024 show the following: -

- 1) Depths of between 1.7 and 2.0 metres below Chart Datum have encroached up to 75 metres into the Eastern edge of the channel from 50 metres downstream to 235 metres upstream of the FH3 Light Buoy.

Deeper water exists to the West in this vicinity.

- 2) A least depth of 1.9 metres below Chart Datum exists on the Eastern edge of the channel 680 metres downstream of the FH5 Light Buoy.

Deeper water exists to the West in this vicinity.

- 3) Depths of less than 2 metres below Chart Datum exists on the Eastern edge of the channel from 110 metres to 375 metres upstream of the FH7 Light Buoy.

Deeper water exists to the West in this vicinity.

MARINERS ARE ADVISED that 1.5 metres below Chart Datum should be used for passage planning purposes and Notice to Mariners No. H. 52/2024 is hereby cancelled.

**CAPT. A. FIRMAN
HARBOUR MASTER, HUMBER**

2nd August 2024

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

www.humber.com