

# **NOTICE TO MARINERS**

---

**No. H. 15/2026**

**RIVER HUMBER**

**GRIMSBY MIDDLE DEPOSIT  
SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 26<sup>th</sup> January 2026 shows the following: -

A shoal with a least depth of 1.3 metres below Chart Datum exists in the South-East corner of the Grimsby Middle deposit spoil ground 485 metres downstream of the P7 Light Buoy.

**MARINERS ARE ADVISED** that depths within spoil grounds are inevitably subject to change and should therefore proceed with caution in these areas. In addition, Notice to Mariners No. H. 122/2025 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

27<sup>th</sup> January 2026

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)