

---

# NOTICE TO MARINERS

---

**No. H. 14/2026**

## RIVER HUMBER

### HULL ROADS – EAST MIDDLE - SHOAL WATER

**MARINERS ARE WARNED** that a survey carried out on the 22<sup>nd</sup> January 2026 shows the following: -

- 1) Depths of between 4.3 metres and 5.5 metres below Chart Datum have encroached up to 30 metres into the Northern edge of the channel from 460 metres downstream to 115 metres upstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of between 4.4 metres and 5.5 metres below Chart Datum have encroached up to 15 metres into the Northern edge of the channel from 200 metres to 380 metres upstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity.

- 3) Depths of between 4.9 metres and 5.5 metres below Chart Datum have encroached up to 50 metres into the Southern edge of the channel from 200 metres downstream of the East Middle Light Buoy to 110 metres downstream of the No. 22 Hook Light Buoy.

Deeper water exists to the North in this vicinity.

- 4) Depths of between 4.7 metres and 5.5 metres below Chart Datum have encroached up to 63 metres into the Southern edge of the channel from 630 metres downstream to 45 metres upstream of the No. 24 Lower West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 172/2025 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

23<sup>rd</sup> January 2026

THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)