

---

# NOTICE TO MARINERS

---

No. H. 32/2026

**RIVER HUMBER**  
**GRIMSBY MIDDLE - SHOAL WATER**

**MARINERS ARE WARNED** that a survey carried out on the 2<sup>nd</sup> March 2026 shows the following: -

- 1) Depths of less than 6.4 metres below Chart Datum have encroached up to 55 metres into the Southern edge of the navigation channel from 550 metres to 1080 metres downstream of the No. 4B Light Buoy.

Deeper water exists to the North in this vicinity.

- 2) Depths of less than 6.4 metres below Chart Datum have encroached up to 95 metres into the Southern edge of the navigation channel from 100 metres upstream of the No. 6 Lower Burcom Light Float to 830 metres downstream of the Pyewipe Outfall Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of less than 6.4 metres below Chart Datum have encroached up to 50 metres into the Southern edge of the navigation channel from 450 metres to 730 metres upstream of the Pyewipe Outfall Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 94/2025 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

3rd March 2026

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)